

GM 4L60E/4L65E (2000-2007) TORQUE CONVERTER



GM92 FEATURES:

- ▶ 100% custom impeller hub replacement to correct build height issues

COMMON FAILURES:

Build height from GM is 0.050" too short, which prevents proper mating to the oil pump assembly

SOLUTION:

100% correction of all build heights



EACH RECON™ BY TRANSTAR TORQUE CONVERTER IS COVERED BY THE INDUSTRY-LEADING 3-YEAR, 36,000-MILE WARRANTY!*

**Recon by Transtar Torque Converter Limited Warranty*