

A4LD, 4R55E, 5R55E, 5R55W/S (1992-2006) TORQUE CONVERTER



FM68HD FEATURES:

100% upgrade to late design internal components

- ▶ Heavy duty bearing on impeller side
- ▶ Phenolic stator cap on turbine side
- ▶ Heavy duty hardened turbine splines
- ▶ Fins are brazed or welded

COMMON FAILURES:

- ▶ Weak damper design
- ▶ Weak damper to turbine hub interface

SOLUTION:

- ▶ Replacement of all dampers with OE LuK heavy duty damper
 - Converted from the weaker 8-spring design to the more durable 6-spring damper design

EACH RECON™ BY TRANSTAR TORQUE CONVERTER IS COVERED BY THE INDUSTRY-LEADING 3-YEAR, 36,000-MILE WARRANTY!*

**Recon by Transtar Torque Converter Limited Warranty*